

Table of Contents

1 Introduction and Materials

1·1	Overview	1
1·2	Machine Axes	1
1·3	X Axis	2
1·4	Y Gantry	2
1·5	Z Carriage	3
1·6	Tools and Materials Overview	3
1·7	Tool List, Required	5
1·8	Sizes of Materials	5
1·9	Materials	6
1·10	Basic Machine, Cut 1x4	8
1·11	Table Bed Materials	9
1·12	Machine and Table Bed, Cut 2x4	9
1·13	Stand, Cut 1x4	9
1·14	Wood Notes	10
1·15	Hardware Notes	10
1·16	Cut Pipe	11
1·17	Kitchen Cutting Board	11
1·18	Bearings	11
1·19	Leadscrews and Leadnuts	12
1·20	Upgrading	13
1·21	Suppliers	14
1·22	Leadscrew Parts	14

2 Stand and Bed

2·1	Router Stand Overview	15
2·2	Stand Construction	15
2·3	Table Bed Overview	19
2·4	Table Bed Frame	19
2·5	Wood Note	20
2·6	Table Bed 1x4 Slats	21
2·7	Table Bed Assembly	21
2·8	Attach Bed to Stand	22

3 X Axis Frame and Rails

3·1	X Axis	23
3·2	X Axis Pipe Rails	23
3·3	X Threaded Studs	24
3·4	Install Studs in Pipes	24
3·5	Rail Supports	24
3·6	Install Rails	25

3·7	1x4 Cross Members	26
3·8	Bearing Recesses	26
3·9	Stepper and Idler Holes	27
3·10	1x4 for Closed Front Machine	28
3·11	1x4s for Open Front Machine	28
3·12	Machine Legs	29
3·13	X Axis Assembly	29

4 Y Gantry

4·1	Y Gantry Overview	31
4·2	Y Pipe Rails	31
4·3	Y Threaded Studs	31
4·4	Install Studs in Pipes	32
4·5	Gantry Beam	32
4·6	Install Y Rails on 2x6 Beam	32
4·7	End Plates	33
4·8	Right (Stepper) End Plate	33
4·9	Left End Plate	35
4·10	Attach End Plates to Gantry	36
4·11	X Bearings Overview	36
4·12	Wooden Outriggers	37
4·13	Fabrication of Outrigger Blocks	38
4·14	Metal Outriggers	38
4·15	Install Carriage Bolts	39
4·16	Install Bottom Bearings	39
4·17	Install Gantry on X Axis	40
4·18	Install Leadnut Carriage Bolts	42
4·19	Gantry Review	42
4·20	Note for Solid Sheet Table Bed	42

5 X Leadscrews

5·1	X Leadscrew Components Overview	43
5·2	X Bearing Flanges	43
5·3	X Leadnuts Overview	44
5·4	Leadnut Options	44
5·5	Hole Alignment	45
5·6	Holes in Leadnut	45
5·7	Bracket Trim Note	46
5·8	Aluminum Brackets	46
5·9	Attach Leadnuts to Brackets	47
5·10	Install Leadscrew	47
5·11	Mark and Drill Bracket	47

5-12	Align Leadscrew	48
5-13	Install Pulleys and Clamps	49
5-14	X Belt Overview	50
5-15	Idler	50
5-16	Install Stepper	51
5-17	Move Gantry	52
5-18	Install Belt	52
5-19	Tighten Stepper and Belt	52
5-20	Square Gantry	53
5-21	Adjust Gantry Front Bearings	53
5-22	Bearing Tensioning	54
5-23	Review	54

6 Z Carriage Body

6-1	Z Carriage Overview	55
6-2	Y Bearing Trucks	55
6-3	Measure Distance Between Trucks	56
6-4	Y Leadnut	56
6-5	Side Plates	57
6-6	Back Plates	58
6-7	Top Plate	58
6-8	Bottom Plate	60
6-9	Install Bottom Truck	60
6-10	Install Top Truck	61
6-11	Install Y Tension Rods	62
6-12	Z Bearing Flange	63
6-13	Review	64

7 Y Leadscrew

7-1	Leadscrew to Stepper Coupler	64
7-2	Y Bearing Flange	65
7-3	Install Y Leadnut	65
7-4	Install Y Leadscrew	65
7-5	Install Y Stepper	66

8 Z Axis

8-1	Install Z Stepper	68
8-2	Z Bearing Trucks	69
8-3	Attach Z Trucks	69
8-4	Z Leadscrew Overview	70

8-5	Leadnut and Bracket	70
8-6	Install Z Leadscrew Assembly	71
8-7	Spindle Plate and Rails Overview	71
8-8	Spindle Plate	72
8-9	Porter Cable 7301	72
8-10	Spindle Plate Stud	73
8-11	Band Clamp	73
8-12	Z Pipe Rails	74
8-13	Attach Pipes to Plate	75
8-14	Cross Tie	75
8-15	Install Z Rails	76
8-16	Tension Rods	76
8-17	Align Z Rails and Trucks	77
8-18	Attach Bracket, Align Flanges	77
8-19	Tighten Z Stepper	78

9 Software Settings

9-1	Software Settings, Introduction	79
9-2	Steps per Revolution, Stepper	79
9-3	Micro-Stepping	79
9-4	Leadscrews	80
9-5	Starts, and Turns per Inch	80
9-6	Determining Steps per Unit	80
9-7	Resolution	80
9-8	Axis Names	81
9-9	Switch X and Y Axis Names	81
9-10	Speed (Velocity) and Acceleration	82
9-11	Tuning	83
9-12	Wrap Up	84

10 Templates

X 1x4 Bearing Recesses	85
X 1x4 Stepper Mount	85
X 1x4 Front Horizontal and Legs	87
Y End Plate Right	89
Y End Plate Left	91
Z Side Plate Right	93
Z Side Plate Left	95
Z Top Plate	97
Z Bottom Plate	97
Bearing Flanges	99